


1	2	3	4	5	6
		RevNo	Revision note	Date	Signature
					Checked







WARNING: Do not use ferrules  
cable should go directly into the  
terminals

- \* Strip Length 8-10mm
- \* Max Cross Section 1mm<sup>2</sup>
- \* Fuse the 24VDC input 0.5amps
- \* Solid Wire: push directly into contact
- \* Stranded Wire:
  1. Push release button
  2. Push in the wire



SCALE 1:1



Itemref	Quantity	Title/Name, designation, material, dimension etc			Article No./Reference
Drawn by Kevin Damen	Checked by	Approved by - date	File name	Date 7-8-2023	Scale 1:1

152

www.damencnc.com

152 ITP16-G Temperature Indicator PT100 PT1000 TC-K TC-J (GREEN)	Edition	Sheet 1 OF 1
---	---------	-----------------

Units: mm Tolerances: +/- 0.2mm